


Solid State Sensors  
Digital Position Sensors

SR3 Series




FEATURES

- Completely enclosed housing
- Color coded leadwires
- High speed, no-touch operation over 100 kHz possible
- Adjustable mounting
- Reverse polarity protection (bipolar listing)
- Meets NEMA 3, 3R, 3S, 4, 4X, 12 and 13 requirements
- Bushing is PBT (Valox 420 SEO) 30% glass filled

MOUNTING DIMENSIONS

(For reference only)





24AWG Leadwire color code:


- Red Vs (+)
- Green Output
- Black Ground (-)

MOUNTING BRACKETS

1SR14M



1SR14MHD



SR3 ORDER GUIDE

Catalog Listings			SR3F-A1	SR3B-A1	SR3G-A1	SR3C-A1	SR4P2-A1
Supply Voltage (VDC)			4.5 to 24	4.5 to 24	4.5 to 24	4.5 to 24	6 to 24
Supply Current (mA max.)			18.0	15.0	22.0	19.0	13.5
Output Type			Sink	Sink	Sink	Sink	Sink
Output Voltage (V max.)			0.40	0.40	0.40	0.40	0.40
Current per Output (mA max.)			10	10	10	10	20
Magnetics Type			Unipolar (1)	Bipolar (2)	Unipolar (1)	Unipolar (1)	Omnipolar (3)
Magnetic Char. & Temp.	−40 to 85°C (−40 to +185°F)	Max. Op.	G    mT 450   45.0	G    mT 150   15.0	G    mT 430   43.0	G    mT 190   19.0	G    mT 25    2.5
		Min. Rel.	170   17.0	−150 −15.0	160   16.0	60    6.0	5     0.5
		Min. Dif.	20    2.0	40    4.0	50    5.0	10    1.0	7     0.7
	25°C (+77°F) Typical	Typ. Op.	400   40.0	90    9.0	350   35.0	150   15.0	15    1.5
		Typ. Rel.	185   18.5	− 90 − 9.0	280   28.0	100   10.0	11    1.1
		Typ. Dif.	20    2.0	80    8.0	70    7.0	30    3.0	4     0.4

- (1) A unipolar sensor has a plus maximum operate point and a plus minimum release point. One magnetic pole (south) is required to operate and release a unipolar sensor.
- (2) A bipolar sensor has a plus (south pole) maximum operate point and a minus (north pole) minimum release point. Operate and release points can be both positive, or both negative. **Latching cannot be guaranteed.** Ring magnets are usually used with bipolar sensors.
- (3) An omnipolar sensor operates with any magnetic field (north or south pole).
- (4) Operating characteristics are from -20°C to +85°C for SR4P2-A1.
- (5) To order 1 meter jacketed leads, replace the 1 at end of listing with a 2.  
Example: SR3B-A2.  
G = Gauss  
mT = milliTesla