



Digital Dial Indicator 1075 Millitast

with

marconnect

Digital Dial Indicator 1075 Millitast and **marconnect** – the innovative and efficient connection for data processing.

marconnect transmits your data directly and reliably via the electronic standard interfaces OPTO-RS-232C and Digimatic to a PC or printer. Just as required.




<http://www.mahr.com>

Digital Dial Indicator 1075 Millitast



- 1 Protective and lifting cap for measuring spindle
- 2 Display
- 3 Operating buttons
- 4 Mounting shank
- 5 Measuring spindle
- 6 Contact point 901
- 7 Data output
- 8 Battery compartment



Features

- Functions: ON/OFF
- 0 (Zero Setting)
- mm/inch
- Reversal of counting direction
- PRESET (for entering any numerical value)
- DATA (in connection with data connecting cable)
- Capacitive measuring system, life of battery approx. 2.5 years
- Measuring speed 1,5 m/s (60"/s)
- Data output: optional OPTO RS232C or Digimatic
- High contrast LCD-display with 8,5 mm high numerals
- Protective housing (back wall integrated in housing)
- Raising of measuring spindle via lifting cap or cable release 951 (accessory)
- Operating temperature 10-40°C
- Class of protection IP 51 as per IEC 529
- Standard accessory: Case and battery


Technical Data

	Range	Resolution	Span of error f_e^*	Measuring force	Weight	Order no.	Remarks
	mm (inch)	mm/inch	mm (inch)	N	g		
1075	12,5 (.5")	0,01 / .0005"	0,03 (.0015")	0,7 - 1,1	110	4336400	
1075 L	12,5 (.5")	0,01 / .0005"	0,03 (.0015")	0,7 - 1,1	120	4336410	with mounting lug 3/8" mounting shank

*indicated value + 1 resolution

Accessories

	Order no.
Battery 3V , type CR 2032	4102520
Data connecting cable Opto RS232C (2m), with SUB-D jack 9-pin	16 Exr 4102410
Data connecting cable Digimatic (2m), Flat connector 10-pin	16 Exd 4102411
Adapter bush for adapting mounting shank 8h6 to inch bore .375"	940 4310103
Cable release for lifting measuring spindle	951 4372000
Mounting lug for mounting on mounting shank 8h6 mm	963 4375002



Data Connecting Cable 16 EXr/16 EXd
with data button

For more accessories see General Catalogue „Dimensional Metrology - Hand Measuring Instruments“

		page
Contact points	901-913	3-26
Special holder	941	3-27
Sensor lever	943	3-27

Accessories for data processing see chapter 9